



Three-phase motor for 2 speeds  
with 2 separate windings

Conn. diagram  
KP 0006



For pole-changing-switch all terminals must be connected with it.

			Datum	03.01.2005		
			Bearb	Kresse		
			Gepr			
			Norm			
			 Elektromotorenwerk Wernigerode		Zeichnungs-Nr.	Blatt
01					KP 0006 e	
Zust	Mitteilung	Datum	Name			